

Operating Instructions

Digital Optical Tachometer

Advent Series Models

A2102,A2102/LSR

A2103,A2103/LSR

Part no: 13650 issue 2.3

Operating instructions for Advent Hand Tachometer models A2102, A2102/LSR A2103, A2103/LSR

General features of models

All models feature a patented **vertical LCD display** that gives very good view in most applications, all have an "**Inverting display feature**" which maintains the display in the correct plane for the user, for example when pointing the unit down into machinery.

A2102 versions, both models include the unique display inverting feature for greater flexibility in operation in almost any application where access is difficult within confined areas, the **A2102/LSR** Laser version provides enhanced optical performance, both are supplied with a Contact adaptor for rpm & linear speed contact applications.

Both A2103 models feature comprehensive specifications, including Maximum and Minimum speed Capture and Average speed modes, model A2103 has the standard visible incandescent Minilamp and model A2103/LSR has an enhanced Laser light system for even wider application and greater performance.

Models A2102 and A2102/LSR features and operation

Optical systems - Two types of optical system are used: -

Model A2102 has the standard visible light source via an incandescent Minilamp

Model A2102/LSR has enhanced optical Laser light system for greater optical performance.

Both models have a fully autoranging measurement system as standard.

Common Display features & Specification - Models A2102 & A2102/LSR

Display - Inverting LCD Vertical 5 digit display

Display functions - 180 deg. Inverting

On target indicator - Yes Low Battery indicator - Yes

Function icons - "rpm" & "mt" for metres/minute

Controls - 3 push-buttons

On/off normal mode - Dual action rocker type touch push-button

(UP ARROW)

On/off inverted mode - As above but for inverted operation (DOWN ARROW)
Program control - Selects rpm or metres/minute modes (mt symbol)

Optical system - model A2102

Optical range - 50mm - 1000mm

Optical angle - +/- 45 Deg. to reflective marker

Light source - Minilamp visible light

Optical system - Laser model A2012/LSR

Optical range - 50mm - 2000mm

Angle of operation - +/- 80 Deg. to reflective marker
Light source - Red Spot Laser Class II (670nm)

Measurement range - both models

Measurement ranges - rpm (optical) & rpm or metres/min with contact adaptor supplied.

Autoranging function - Autoranging only

Speed range rpm - 3 - 99,999 rpm (50,000 rpm for 10 secs in Contact mode)

Linear Metres/min - 0.30 - 1999.9 metres/min + Contact adaptor

Resolution maximum - 0.01 in slowest speed range

Accuracy - 0.02% +/- 1 digit

Timebase - 0.8 seconds or time between pulses, whichever is longest

Operation and Use of Models A2102 & A2102/LSR

Optical rpm measurement

- 1. Ensure the machine to be measured is in a safe off mode.
- 2. Attach small reflective target to machine shaft (typically 6mm x 25mm.less for laser).
- 3 Start machine and point the Tachometer at the target.
- 4. Press and hold continuously either of the On/Off buttons to suit application.
- 5. Aim light beam onto target, ensure "on-target" sign is glowing or flashing steadily.
- 6.Read rpm, releasing button will hold last reading in the display for 1 minute.
- 7. Press either On button to zero reading or take another measurement.

Contact rpm measurement

- 1. Fit contact adaptor into the Tachometer and ensure a good click fit connection.
- 2. Start machine and make clean contact with the shaft end.
- 3. Ensure a steady firm pressure is applied to the wheel, just sufficient to maintain slip free contact, excess pressure will wear the rubber tip and bearings and may slow the machine down and give inaccurate readings.
- 4. Releasing the On/Off switch will hold the reading automatically for 1 minute.

Linear contact speed measurement - Metres/minute

- 1. Fit contact adaptor as above.
- 2. Press and hold the On button, then press the program button, the display will alternate between the "**rpm and mt**" symbols, release the program button when the "**mt**" symbol is illuminated, the instrument is now in the metric linear speed.
- 3. Keeping the On button pressed, now place the contact wheel on the moving surface and read th linear rate.
- 4. Releasing the On button will then hold the last reading in the display for 1 minute.
- 5. The instrument retains Metres/min ode for continued linear measurments for up to 1 minute from previous reading, by pressing either "Measure" buttons this mode will be held for a further minute.
- 6. The instrument will automatically revert to rpm mode after auto switch off.

Note: Inverted operation

The instrument can be used through 180 deg. rotation (e.g. with the light beam or contact probe pointing downward into a machine), the display inverts so display reading is clear.

Models A2103 & A2103/LSR features and operation

Common Display features & Specification

Display - Inverting LCD Vertical 5 digit display

Display functions - 180 deg. Inverting

On target indicator - Yes Low Battery indicator - Yes

Function icons - Comprehensive selection of ranges shown in display

Controls - 3 push-buttons

On/off normal mode
On/off inverted mode
On/off inverted mode
Program control

- Dual action rocker type touch push-button (UP ARROW)
- As above but for inverted operation (DOWN ARROW)
- Selects program mode in conjunction with Up/Down switches

Optical system Model A2103

Optical range - 50mm - 1000mm

Optical angle - +/- 45 Deg. to reflective marker

Light source - Minilamp visible light

Optical system - Laser model A2103/LSR

Optical range - 50mm - 2000mm Angle of operation - +/- 80 Deg.

Light source - Red Spot Laser Class II

Measurement range - both models

Measurement modes - rpm & rps optically (also Count & Time)

- rpm & rps, metres, yards, feet, per min & per sec, via contact

adaptor

- Count total revs, metres, feet, yards
- Measure Time interval in seconds between pulses (reciprocal rate)
 Speed Capture feature Maximum, Minimum or Average rate

Contact mode

Speed range - Optical mode - 3 - 99,999 rpm (or equivalent in rps)

- Max. 50,000 rpm for 10 sec (or equivalent in rps)

Linear speeds - maximum onds

- 0.30 - 1500.0 Metres or Yds/min. (4,500 ft/min) or equilavent in sec-

- Fully Autoranging up to 0.001digit or +/- 1 digit fixed, User selectable

Resolution range features Accuracy speed modes only

- 0.02% +/- 1 digit

Count mode resolution Time interval mode

- +/- 0.1 Metres (or equilavent in all ranges) - 0 - 99999 seconds Autoranging only (max 0.01 resolution)

Timebase standard

- 0.8 seconds or time between pulses, whichever is longest

Timebase, Fast modes Memory features

- 0.1 seconds auto-selection in Maximum or Minimum capture mode

- Last reading held for 1 minute, Auto Switch Off

- Program settings retained in memory after power down off

Contact adaptor

- Included complete with rpm cone & metric wheel assembly (remova

ble)

Ex works setting - rpm mode, non autoranging

1. Programming - measurement mode selection

All measurement modes are chosen by this method and once confirmed, selected mode remains in permanent memory until re-programmed by the user.

- 1.1. To change mode hold programme button on and press up measure button and then release both buttons, the display will now illuminate all icons, and the current range will flash.
- 1.2. To select new measurement mode press either up or down button to scan through the modes, when the required mode icons flash release measure button & press programme button once to confirm settings.

for non-speed modes the unit is now programmed and read for use.

1.3. To select mx, mn, av. modes continue to scan through each one, if the mode is not required, stop scan when all three icons illuminate continuously, then press programme button once.

The instrument is now ready to use. **Set parameters will be retained until reprogrammed.**

2. Optical revolutions speed measurement - rpm or rps.

- 2.1. Ensure batteries are correctly fitted.
- 2.2. Attach small reflective target to machine shaft (typically 6mm x 25mm, less for laser version)
- 2.3. Start machine and point the tachometer towards the target.
- 2.4. Press and hold either of the on/off buttons to suit application and hold continuously.
- 2.5. Aim light beam onto target, ensure "on-target" sign is glowing or flashing steadily
- Read off rpm, releasing button will hold last reading. 2.6.
- Last rpm reading will be held in display for 1 minute. 2.7.
- 2.8. Press the On button to zero reading or take another measurement.

3. Contact revolution speed measurement - rpm or rps.

- 3.1. Fit contact adaptor into the tachometer and ensure a good click fit connection.
- 3.2. Start machine and make clean contact with the recess in shaft end (wheel can be removed).
- 3.3. Contact the shaft end via the rubber cone, ensure a steady firm pressure is applied and that the instrument is in line accurately with the machine shaft.
- 3.4. Press and hold either up or down measure button as required & read speed
- 3.5. Releasing the On switch will hold the reading automatically for 1 minute, automatic switch off.

4. Linear contact speeds measurement - metres, vds, feet etc.

- 4.1. Fit contact adaptor as above.
- 4.2. Keeping the on button pressed, now place the contact wheel on the moving surface and read the linear rate, ensure wheel is vertical to the moving surface.
- 4.3. Releasing the on button will then hold the last reading in the display for 1 min.
- 4.4. The instrument retains selected measurement mode for further linear measurements after switch off until programmed to a different mode.

5. Autorange selection - speed modes only

5.1. While taking a measurement using either up or down measure button, the user can toggle between auto and non-auto mode by pressing the programme button, in the auto mode, the a icon will illuminate.

6. Average speed monitoring mode - 'av' icon.

- 6.1. **Average speed mode** this mode provides a rolling average of the last 8 measured values.
- 6.2 Press and hold the On/off button at the forward arrow position and hold continuously
- 6.3 Aim light beam onto target, ensure "on-target" sign is on at bottom of display screen.
- 6.4 Take rpm reading.
- Note that the display will illuminate only while measurement is taking place.
- 6.6 Release on/off button and display will clear no memory retention is available.

7. Operation of Maximum & Minimum modes Speed Capture functions - mx,mn.

- 7.1. Having selected the required mode, i.e. Maximum or Minimum, (mx).
- 7.2. You are now ready to Capture a reading "On Demand" but continuing to operate normally.
- 7.3. When a capture test is ready to commence, while the Measure button is held On, press Programme button once, at this point the instrument will switch into high speed Timebase mode, (0.1 Seconds) and will Capture the highest or lowest reading after pressing the Programme button.

Releasing the On button will hold the reading and cancel the Capture mode until another Capture measurement is required, when 7.3. should be repeated.

8. Count measurement mode - cnt

- 8.1. Select mode as described in Measurement mode selection section
- 8.2. For rev Counting optically, point the light beam at the target and the instrument will measure all revs. (pulses) until button is released, the display will hold Count for 1 minute.
- 8.3. By contact method, fit contact adaptor, press speed cone onto the end of the shaft, the Instrument will count revs.

9. Linear Length Totalisation measurements - mt, ft, yd -

- 9.1. Select any linear unit of measurement, press contact wheel onto moving surface and commence Count by pressing & holding Measure button On, Count will increment until button is released.
- 9.2. The displayed value can be scanned through the equivalent values of Metres, Feet, Yards, Count by pressing the Programming button, the instrument automatically calculates the appropriate reading.

Note. Measurement Units will be stored in originally programmed parameter e.g. metres.

10. Time interval measurement - int

- 10.1. Select int mode through Measurement selection mode
- 10.2. This mode allows measurement of Time between pulses from optical system (or contactor).
- 10.3. Optically the instrument will measure the time in seconds between pulses, useful for cycle timing of reciprocating machinery.
- 10.4. (Time in seconds per revolution), which equals reciprocal speed.
- 10.5. Very slow speeds can be measured in this mode below 3 rpm.

11. Display orientation - Inverting function - All modes

- 11.1. The instrument can be used through 180 deg. rotation (e.g. with the light beam pointing downward into a machine), the display inverts so that normal reading can take place.
- 11.2. The UP Button selects normal mode for optical and contact measurements.
- 11.3. The Down button selects the display inversion mode and the whole display including relevant icons will reverse through 180 degrees allowing access to difficult applications.

Temperature specification and storage (LCD Display)
Operating temperature = 0 to + 50 ° C.
Storage temperature = -10 to + 80 ° C.